

## **EQUIPMENT AND ACCESSORIES LISTING**

The following is a partial listing of equipment and accessories that will assist the applicator in the installation of Flex Single Ply Roofing Systems

### **GENERAL EQUIPMENT**

- Clean, asphalt-free extension cord of adequate sizing to handle power requirements
- One (1) pair of scissors per man
- Tape measures, varying up to 100 feet in length
- Chalk boxes, chalk
- Four inch (4") wide paint brushes
- Clean cotton rags
- Caulking guns
- Push Brooms
- Non-permanent ink or crayon writing element for marking seams
- Several Flex Seam Probes for probing of seams
- Clean, asphalt free waterproof canvas or tarp for covering of materials
- Several one and one-half inch (1 1/2") wide silicon hand rollers
- Several standard screw guns w/ disengaging clutch (1800-2500RPM)
- One 1/2 inch (1/2") nap paint rollers w/ solvent resistant cores and handles
- Hammers, screwdrivers, sockets, allen wrenches and drill bits
- Utility knife, hook blades, straight blades
- Approved fasteners and plates
- Approved cleaners or solvents
- Approved caulking or sealant
- Wire brushes for cleaning welder tips
- Assortment of tips or nozzles for hand held hot air welder
- Hammer drill or Tapcon Anchor driver
- Notched squeegee for applying substrate adhesive
- 200 pound roller for proper adhesion of Flex FB adhered system

### **WELDING EQUIPMENT**

- A. Leister Varimat automatic welding machine, requires 230 volt, 4600 watt power Leister Triac hand held hot air welder, requires 120volt, 1600-watt power
- B. Portable Electric Generator: minimum output of 9500 watts to adequately provide power to operate one automatic hot air welder and one hand held hot air welder.